



FIG.1




2/17

FIG.2




3/17

FIG.3




4/17

FIG.4




5/17

FIG.5




6/17

FIG.6




7/17

FIG.7



8/17

FIG.8



9/17

FIG.9A






FIG.9B



10/17

FIG.10



11/17




FIG.11A


FIG.11B

FIG.11C

FIG.11D


12/17

FIG.12




13/17

FIG.13




14/17

FIG.14



15/17



$$\text{Lap}(\%) = W_s / W_{c0} \times 100\%$$

FIG.15A





FIG.15B

16/17

FIG.16



17/17

FIG.17

